

Fig. 9-3. Properly prepared joint.




Fig. 9-4. Improperly prepared joint. — too shallow.




Fig. 9-5. Improperly prepared joint. — furrow should be eliminated.




Fig. 9-6. Improperly filled joint.




Fig. 9-7. Concave joint.




Fig. 9-8 V-joint.




Fig. 9-9. Weeping mortar joint.




Fig. 9-10. Beaded mortar joint.




Fig. 9-11. Raked mortar joint.




Fig. 9-12. Flush mortar joint




Fig. 9-13. Struck mortar joint.




Fig. 9-14. Weathered mortar joint.